



1 Main barn consists of CMU foundation, wood framing/metal siding, metal roof over wood shingle. It is in poor condition with water and structural damage.



2 Deteriorating roof on main barn. Assume wind damage to metal roof.




3 Structure consists of reinforced concrete. It is in fair condition. Will acquire additional structural study.



4 Structure consists of wood framing, painted brick, painted wood siding, metal roof. It is in good condition.



5 Secondary barn consists of CMU foundation, wood framing/siding with metal roof. It is in poor condition with water damage.



6 Structure consists of steel frame with aluminum wall and roof panel. It is in good condition.