



REMEDIATION UPDATE

PETERS CARTRIDGE SITE AUGUST 2015

King Mills, Ohio



The Little Miami River flows past the Peters Cartridge site, parallel to the Multi-Use Trail.

TRAIL CONTINUES TO BE OPEN AS NOTED THROUGH AUG. 31

Periodic, short term closures for remediation-related work activities planned during this time

The Little Miami Multi-Use Trail between mile markers 35.0 and 35.5 is currently OPEN through AUGUST 31, 2015.

(On certain days, it is anticipated that there will be periodic, short-term (up to 20 minutes) closures (indicated by flag persons) for Peters Cartridge site remediation-related work activities that may be planned.

(These periodic, short-term closures will only occur when needed to safely move equipment and materials across the trail.) We apologize for any inconvenience this may cause.

Users planning to traverse the Trail between mile markers 35.0 and 35.5 are advised to call the **24/7 “Trail Hotline” phone number (513-552-7030)** for ongoing updated information.

AUGUST UPDATE



REMEDIATION PROGRESS HIGHLIGHTS

- Approaching 15,000 safe work hours!
- Completed AOC 9 trash load out and disposal.
- Over 9,500 tons of non-hazardous trash hauled to a licensed, off-site, waste management facility.
- Beginning AOC 9 trash area restoration.
- Completed consolidation cell liner base clay installation.
- Ready for installation of synthetic consolidation cell liner.
- Continuing stabilization of high lead areas.



Summit continues load out of AOC 9 non-hazardous debris and soil.

CONTACTS

Clint Betchan, On-site Manager – Parsons
Clinton.betchan@parsons.com
405-496-8648

Peter Ciotta, Communications Manager - DuPont
716-879-1846
Peter.J.Ciotta@dupont.com



2443 Crowne Point Dr.
Cincinnati, OH 45241

Follow DuPont Operations on Twitter
http://twitter.com/DuPont_NAOps

To receive 'DuPont Remediation Update'; please
send email to: Peter.J.Ciotta@dupont.com

WORKING SAFELY

APPROACHING 15,000 SAFE WORK HOURS!

The Peters Cartridge Site Remediation Team continued its outstanding safety performance and is rapidly approaching 15,000 safe work hours!



Soil samples taken behind building R2 and sent for geotechnical analysis to Bowser Morner.



Parsons collecting AOC 9 grid confirmation samples.

Committed to ZERO

*THROUGH THE SUMMER
WITH ZERO ACCIDENTS*

SAFETY TIP

Committed to ZERO **OFF JOB**

**NEVER ALLOW CHILDREN
TO OPERATE LAWN MOWERS**

- Never allow children to ride on lawnmowers or to play near motorized lawn equipment.
- Do not allow children under age 12 to operate push mowers and do not allow children younger than 16 to operate ride-on lawnmowers.



Structure Environmental staff investigating thickness of asbestos-containing tar paper from behind building R3.
(Photo taken looking west.)

AUGUST UPDATE



Aerial view showing removal of AOC9 trash in the foreground and consolidation cell at top of photo.



View looking north at completed AOC 9 trash removal.

AUGUST UPDATE



Summit vehicles transporting clay fill to cell. Two dump trucks being filled with excavator for clay lifts. Tractor with scraper transporting clay fill to cell berm walls for liner anchor trench buildup. Water truck keeping dust down along haul path to cell. (Looking west to stockpile)

Consolidation cell clay liner re-conditioning complete. (Looking North)



PETERS CARTRIDGE SITE REMEDIATION UPCOMING WORK ACTIVITY

Date	Work Action
THROUGH AUGUST 31	TRAIL OPEN AS NOTED
Ongoing	<ul style="list-style-type: none">• “100 Days of Summer” focus on safety.• AOC 9 trash area restoration.• Installation of consolidation cell liner and leachate collection system.• Stabilization of high lead areas.



The DuPont Corporate Remediation Group and project partner Parsons were very pleased to host Ohio EPA representatives for a mid-July walking tour of the former production areas, AOC 9 and consolidation cell.

